



# KENCRO

## CHEMICALS

### SPECIFICATIONS: SULPHURIC ACID 50%

Parameter	Limits
Assay (as % H <sub>2</sub> SO <sub>4</sub> )	49.0% to 51.0%
Iron (Fe)	50 ppm max
Degrees Baume	40.6 to 42.1
Appearance	Clear, colourless liquid

### SAFETY

As with any chemical, Sulphuric Acid requires care in handling. It is suggested that anyone involved with the procurement or handling of this chemical be familiar with the appropriate safety and handling precautions. Such information is available on the appropriate material and safety data sheet.

***FOR FIRE, HEALTH, SAFETY, AND FIRST AID INFORMATION, PLEASE REFER TO MSDS  
All statements, information, and data presented are believed to be accurate and reliable but  
are presented without guarantee, warranty, or responsibility***

Note: All quantities are reported on a wt./wt. Basis.

**SPEC#: NFAIAI**